

405AR & 422AR Part Number Obsolescence

Notice

Please note that the part numbers 405AR100S2X & 422AR100S0X are being discontinued and will no longer be available due to supplier parts shortages. The new 405AR and 422AR replacement models will use 5A relays to ensure better availability.

Solution

OLD PART NUMBER	DESCRIPTION	STATUS	SUGGESTED REPLACEMENT	DESCRIPTION
405AR100S2X	On Delay/Interval Timer Contacts: 10A 230VAC/24VDC Supply: 20-240VAC/12-240VDC	EOL (End of Life)	405AR100S5X	On Delay/Interval Timer Contacts: 5A 230VAC/24VDC Supply: 20-240VAC/12-240VDC
			405C100F2X	On Delay/Interval Timer Contacts: 10A 250VAC/30VDC Supply: 24-240VAC/24VDC
422AR100S0X	Repeat Cycle Timer Contacts: 10A 230VAC/24VDC Supply: 20-240VAC/12-240VDC	EOL (End of Life)	422AR100S5X	Repeat Cycle Timer Contacts: 5A 230VAC/24VDC Supply: 20-240VAC/12-240VDC
PCN Link: https://rebrand.ly/405AR_422AR_PCN				

Change Summary

Electrical-Wiring

Pin-out, wiring, and other ratings for the 405AR and 422AR 5A models will remain the same.

Pin-out and wiring for the 405C100F2X are the same as the 405AR but with 10A contacts and 24-240VAC / 24VDC power supply requirement.

Physical/Mounting

None.

Configuration

None.

Ratings

Contact ratings will change from 10A to 5A on the 405AR and 422AR suggested replacements.

If 10A is required, the 405C100F2X is recommended.

More Information

For more information, contact ATC Application Engineer, Nathan Personius, at 1-800-727-5646 x209 or npersonius@marshbellofram.com, Customer Service, or your local sales representative.